



28F016XD

SPECIFICATION UPDATE

Release Date: November 1996

Order Number 297555-008

The 28F016XD may contain design defects or errors known as errata. Characterized errata that may cause the 28F016XD's behavior to deviate from published specifications are documented in this specification update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

The 28F016XD may contain design defects or errors known as errata. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications before placing your product order.

* Third-party brands and names are the property of their respective owners.

Copies of documents which have an ordering number and are referenced in this document, or other Intel literature, may be obtained from:

Intel Corporation
P.O. Box 7641
Mt. Prospect, IL 60056-7641

or call in North America 1-800-879-4683, Europe 44-0-1793-431-155, France 44-0-1793-421-777,

Germany 44-0-1793-421-333 other Countries 708-296-9333

Copyright © 1996, Intel Corporation

CONTENTS

REVISION HISTORY	1
PREFACE	3
SUMMARY TABLES OF CHANGES	5
IDENTIFICATION INFORMATION	8
ERRATA	9
SPECIFICATION CHANGES	24
SPECIFICATION CLARIFICATIONS	27
DOCUMENTATION CHANGES	27

REVISION HISTORY

Date of Revision	Version	Description
10/24/94	-001	Document includes all known errata to date (Original Version)
01/23/95	-002	<p>Added:</p> <ul style="list-style-type: none"> Device Version Numbers 01H and 02H. V_{CC} Deep Power-Down Current Queueable Operation Delay after Power-Up and Exit from Sleep, Power-Down, or Reset Completion with Command Error Indication and Invalid Device Operations WP# Control V_{PP} Read Current <p>Deleted:</p> <ul style="list-style-type: none"> Status Register Reads <p>Updated:</p> <ul style="list-style-type: none"> Erase Interruptability <p>Obsoleted:</p> <ul style="list-style-type: none"> Non-Serviced Erase Suspend Command
02/22/95	-003	<p>Added:</p> <ul style="list-style-type: none"> Device Version Number 03H <p>Deleted:</p> <ul style="list-style-type: none"> Erase Interruptability Updating Global Status Register Bits 0 and 1 Active Current Consumption during Sleep Mode V_{PP} Read Current RP# High to RAS# Going Low Word Write Performance <p>Updated:</p> <ul style="list-style-type: none"> Operation Delay after Power-Up and Exit from Power-Down or Reset Completion with Command Error Indication Non-Serviced Erase Suspend Command WP# Control <p>Obsoleted:</p> <ul style="list-style-type: none"> Completion with Command Error Indication WP# Control

REVISION HISTORY, Continued

Date of Revision	Version	Description
06/27/95	-004	Added: Device Version Number 04H. 3.3V V_{CC} Requirement for Optimal Power Savings V_{PP} Voltage Tolerance Requirement for Program/Erase Operations at 3.3V V_{CC} RP# Input Level Control at 5V V_{CC} Write Cycle Timings When Issuing Word Write Commands Components with Fully Programmed and Locked Blocks Non-Serviced Block Erase with Stuck Block Status Register Deleted: Power-Up and Reset Timings Updated: V_{CC} Standby and Deep Power-Down Currents Obsoleted: 3.3V V_{CC} Requirement for Optimal Power Savings Non-Serviced Block Erase with Stuck Block Status Register
12/05/95	-005	Added: 3.3V and 5V V_{CC} DC Characteristics AC Characteristics
07/01/96	-006	This is the new format for the Specification Update document. It contains all identified errata published prior to this date.
08/12/96	-007	Added V_{CC} Standby Current Improvements (I_{CC6} , I_{CC7}) V_{PP} Erase Suspend Current (I_{PPES}) Updated: V_{CC} Deep-Powerdown Current Spec Change (I_{CCD}) V_{CC} RAS# -Only Refresh Current Spec Change (I_{CC3}) V_{CC} Fast Page Mode Current Spec Change (I_{CC4}) Deleted: V_{CC} Word Read Current Errata (I_{CC1}) Errata Access Time from Column Address (t_{AA}) Errata Access Time from CAS# Precharge (t_{CPA}) Errata Access Time from CAS# (t_{CAC}) Errata Access Time from CAS# Precharge (t_{CPA}) Errata
11/11/96	-008	Updated: Device Version Number Device Version Number and FPO Number Relationship Table

PREFACE

As of July, 1996, Intel's Semiconductor Products Group has consolidated available historical device and documentation errata into this new document type called the Specification Update. We have endeavored to include all documented errata in the consolidation process, however, we make no representations or warranties concerning the completeness of the Specification Update.

This document is an update to the specifications contained in the Affected Documents/Related Documents table below. This is the eighth release of the 28F016XD Specification Update. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in Nomenclature are consolidated into the specification update and are no longer published in other documents.

This document may also contain additional information that was not previously published.

Functional descriptions for this product are found in the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet*.

Affected Documents/Related Documents

Title	Order
<i>28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet</i>	290533
<i>16-Mbit Flash Product Family User's Manual</i>	297372

Nomenclature

Errata are design defects or errors. These may cause the 28F016XD's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Changes are modifications to the current published specifications.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation.

Documentation Changes include typos, errors, or omissions from the current published specifications.

NOTE:

Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the product's user documentation (datasheets, manuals, etc.).

SUMMARY TABLES OF CHANGES

The following tables indicate the Specification Changes, Errata, Specification Clarifications, or Documentation Changes which apply to the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet*. Intel may fix some of the errata in a future stepping of the component, and to account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

Codes Used in Summary Tables

Steps

X: Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.

(No mark)
or (Blank box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

Page

(Page): Page location of item in this document.

Status

Doc: Document change or update will be implemented.

Fix: This erratum is intended to be fixed in a future step of the component.

Fixed: This erratum has been previously fixed.

NoFix: There are no plans to fix this erratum.

Eval: Plans to fix this erratum are under evaluation.

Row

| Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

Errata

Number	Device Version Number							Page	Status	Errata
	00	01	02	03	04	05	06			
9600001	X	X	X	X	X	X		9	Doc	3.3V and 5V V_{CC} DC Characteristics
9600002	X	X	X	X				11	Fixed	3.3V V_{CC} Requirement for Optimal Power Savings
9600003	X	X	X	X	X	X		12	Fixed	V_{PP} Voltage Tolerance Requirement for Program/Erase Operations at 3.3V V_{CC}
9600004	X	X	X	X	X	X		12	Fixed	RP# Input Level Control at 5V V_{CC}
9600005	X	X	X	X	X	X		13	Doc	AC Read Characteristics
9600006	X	X	X	X				14	Fixed	Write Cycle Timings When Issuing Word Write Commands
9600007	X	X	X	X	X	X		14	Fixed	Operation Delay after Power-Up and Exit from Power-Down or Reset
9600008	X	X						15	Fixed	Completion with Command Error Indication
9600009	X							19	Fixed	Non-Serviced Erase Suspend Command
9600010	X	X	X	X				22	Fixed	Non-Serviced Block Erase with Stuck Block Status Register
9600011	X	X	X					22	Fixed	WP# Control
9600012		X						23	Fixed	Components with Fully-Programmed and Locked Blocks

Specification Changes

Number	Device Version Number							Page	Status	Specification Change
	00	01	02	03	04	05	06			
001							X	24	Doc	3.3V and 5V V_{CC} DC Characteristics
002							X	26	Doc	3.3V/5V V_{PP} Erase Suspend Current
003							X	26	Doc	AC Read Characteristics

Specification Clarifications

Number	Device Version Number							Page	Status	Specification Clarifications
								26		None in this Specification Update revision.


Documentation Changes

Number	Document Revision	Page	Status	Documentation Changes
		26		None in this Specification Update revision.

IDENTIFICATION INFORMATION

Markings

The Finished Processing Order (FPO) number identifies the device's testing date. The FPO number correlates to a specific Device Version Number, as illustrated below:



FPO Number Location and Clarification

Device Version Number and FPO Number Relationship to Specific Component Stepping

Stepping	Device Version Number ⁽¹⁾	FPO Number	
		Work Week	Year
A-0	00H	≤34	1994
A-1	01H	≥35	1994
	02H	≥01	1995
	03H	≥14	1995
A-2	04H	≥31	1995
A-4	05H	≥09	1996
B-1	06H	≥28	1996

NOTE:

1. Device Version Numbers are based on continuous improvements made in manufacturing and testing of the device and represent the current material shipped.

ERRATA

960001. 3.3V and 5V V_{CC} DC Characteristics

PROBLEM: The following tables list DC characteristics that exceed the maximum specifications published in the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet*.

$V_{CC} = 3.3V \pm 0.3V$, $T_A = 0^{\circ}C$ to $+70^{\circ}C$

3/5# Pin Set High for 3.3V Operations

Symbol	Parameter	Max Spec	Max New	Test Conditions
I_{CC1}	V_{CC} Word Read Current	70 mA	80 mA	$V_{CC} = V_{CC}$ Max RAS#, CAS# = V_{IL} RAS#, CAS#, Addr. Held Valid and Cycling @ $t_{RC} = \text{min}$ $I_{OUT} = 0$ mA Inputs = TTL or CMOS
I_{CC3}	V_{CC} RAS#-Only Refresh Current	70 mA	90 mA	$V_{CC} = V_{CC}$ Max CAS# = V_{IH} RAS# = V_{IL} RAS#, Addr. Held Valid and Cycling @ $t_{RC(W)} = \text{min}$ Inputs = TTL or CMOS
I_{CC4}	V_{CC} Fast Page Mode Word Read Current	60 mA	75 mA	$V_{CC} = V_{CC}$ Max RAS#, CAS# = V_{IL} CAS#, Addr. Held Valid and Cycling @ $t_{PC} = \text{min}$ $I_{OUT} = 0$ mA Inputs = V_{IL} or V_{IH}
I_{CC5}	V_{CC} Standby Current	130 μA	350 μA ⁽¹⁾ 130 μA ⁽²⁾	$V_{CC} = V_{CC}$ Max. RAS#, CAS#, RP# = $V_{CC} \pm 0.2V$ WP#, 3/5# = $V_{CC} \pm 0.2V$ or GND $\pm 0.2V$
I_{CCD}	V_{CC} Deep Power-Down Current	5 μA	350 μA ⁽¹⁾ 10 μA ⁽²⁾	RP# = GND $\pm 0.2V$

NOTES:

- These specification values apply to components with a Device Version Number of 00H.
- These specification values apply to components with Device Version Numbers 01H, 02H, 03H, and 04H.

$V_{CC} = 5V \pm 0.5V$, $T_A = 0^{\circ}C$ to $+70^{\circ}C$

3/5# Pin Set Low for 5V Operations

Symbol	Parameter	Max Spec	Max New	Test Conditions
I _{CC1}	V _{CC} Word Read Current	120 mA	140 mA	V _{CC} = V _{CC} Max RAS#, CAS# = V _{IL} RAS#, CAS#, Addr. Held Valid and Cycling @ t _{RC} = min I _{OUT} = 0 mA Inputs = TTL or CMOS
I _{CC3}	V _{CC} RAS#-Only Refresh Current	120 mA	170 mA	V _{CC} = V _{CC} Max CAS# = V _{IH} RAS# = V _{IL} RAS#, Addr. Held Valid and Cycling @ t _{RC(W)} = min Inputs = TTL or CMOS
I _{CC4}	V _{CC} Fast Page Mode Word Read Current	110 mA	130 mA	V _{CC} = V _{CC} Max RAS#, CAS# = V _{IL} CAS#, Addr. Held Valid and Cycling @ t _{PC} = min I _{OUT} = 0 mA Inputs = V _{IL} or V _{IH}
I _{CC5}	V _{CC} Standby Current	130 μ A	350 μ A ⁽¹⁾ 130 μ A ⁽²⁾	V _{CC} = V _{CC} Max, RAS#, CAS#, RP# = V _{CC} \pm 0.2V WP#, 3/5# = V _{CC} \pm 0.2V or GND \pm 0.2V
I _{CCD}	V _{CC} Deep Power-Down Current	5 μ A	350 μ A ⁽¹⁾ 10 μ A ⁽²⁾	RP# = GND \pm 0.2V

NOTES:

1. These specification values apply to components with a Device Version Number of 00H.
2. These specification values apply to components with Device Version Numbers 01H, 02H, 03H, 04H and 05H.

Upon entering standby and/or deep power-down mode(s), a current surge with a peak amplitude of 200 μ A may occur for a duration of up to 30 seconds. This surge will only happen at most once while in one of these two modes. These errata only affect components listed in the Affected Products section.

Please note that the Reset functionality of the RP# pin is preserved, and it should still be used for the following purposes:

- Write Protection during system power transitions
- Device Reset to read array mode upon exit from deep power-down mode
- Termination of Write State Machine operations upon entry into deep power-down mode

IMPLICATION: The increased current requirements may have an impact on power supply loading or battery life.

WORKAROUND: Ensure that system power supply and/or battery is sufficient to meet the increased current requirements.

STATUS: Plans to fix this erratum are under evaluation.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, 03H, and 04H are affected. (04H eliminates the possibility of a deep power-down current surge). Note that I_{CC5} specifications have returned to datasheet values and I_{CCD} current specifications have been raised for devices with Device Version Numbers 01H, 02H, 03H, and 04H.

960002. 3.3V V_{CC} Requirement for Optimal Power Savings

PROBLEM: When operating at 3.3V V_{CC} , the read voltage (V_{CC}) must ramp to 3.2V or greater (maximum voltage 3.6V) to achieve the published standby current (I_{CC5}) specifications. Once the read voltage crosses this voltage threshold, the V_{CC} tolerance requirement returns to the datasheet specification of $3.3V \pm 0.3V$.

IMPLICATION: If the read voltage (V_{CC}) does not ramp to 3.2V or greater (maximum voltage 3.6V), the increased current consumption may have an impact on power supply loading or battery life.

WORKAROUND: Ramp the read voltage (V_{CC}) 3.2V or greater (maximum voltage 3.6V).

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, 03H and 04H are affected.

9600003. *V_{PP} Voltage Tolerance Requirement for Program/Erase Operations at 3.3V V_{CC}*

PROBLEM: When programming or erasing data at 3.3V V_{CC} (3.3V ± 0.3V) and 5V V_{PP}, the program voltage (V_{PP}) is restricted to 5V ± 0.25V (5%).

IMPLICATION: V_{PP} voltage restriction when programming or erasing data at 3.3V V_{CC} and 5V V_{PP} is impacted.

WORKAROUND: Restrict programming voltage to 5V ± 0.25V when programming or erasing data at 3.3V V_{CC} and 5V V_{PP}.

STATUS: Plans to fix this erratum are under evaluation. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, 03H, and 04H are affected.

9600004. *RP# Input Level Control at 5V V_{CC}*

PROBLEM: The device's RP# input pin must be driven to a minimum V_{IH} voltage of 3.0V when operating at 5V V_{CC}. Therefore, system RP# control logic, if implemented, must drive V_{OH} greater than 3.0V. If such logic is not employed, RP# should be tied to V_{CC} ± 0.2V.

IMPLICATION: Failure to drive RP# to 3.0V could cause the device to stay in reset.

WORKAROUND: When operating at 5V V_{CC}, drive the device's RP# input pin to a minimum V_{IH} voltage of 3.0V.

STATUS: Plans to fix this erratum are under evaluation. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, 03H, and 04H are affected.

9600005. AC Read Characteristics

PROBLEM: The AC Read Specifications that deviate from the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet* are shown below.

$$V_{CC} = 3.3V \pm 0.3V, T_A = 0^{\circ}C \text{ to } +70^{\circ}C$$

Versions		28F016XD-95			
Symbol	Parameter	Min Spec	Min New	Max Spec	Max New
t_{AA}	Access Time from Column Address			75 ns	80 ns
t_{CPA}	Access Time from CAS# Precharge			85 ns	90 ns
$t_{CAS(R)}$	CAS# Pulse Width (Reads)	40 ns	45 ns	∞	∞
$t_{RCD(R)}$	RAS# to CAS# Delay Time (Reads)	15 ns	15 ns	55 ns	50 ns
t_{CAC}	Access Time from CAS#			40 ns	45 ns
t_{CWD}	CAS# to WE# Delay Time	70 ns	75 ns		

$$V_{CC} = 5V \pm 0.5V, T_A = 0^{\circ}C \text{ to } +70^{\circ}C$$

Versions		28F016XD-85			
Symbol	Parameter	Min Spec	Min New	Max Spec	Max New
t_{CPA}	Access Time from CAS# Precharge			70 ns	70 ns ⁽¹⁾ 75 ns

NOTE:

1. High speed test with $V_{CC} = 5V \pm 0.25V$.

IMPLICATION: AC read specifications are impacted.

WORKAROUND: Adhere to modified AC read specifications.

STATUS: Plans to fix this erratum are under evaluation. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, 03H, and 04H are affected.

9600006. Write Cycle Timings When Issuing Word Write Commands

PROBLEM: RAS# rising before CAS#, while OE# is low, at the end of a Word Write command (10H/40H) write cycle may cause high-byte (DQ8-15) data corruption.

IMPLICATION: May cause write failures.

WORKAROUND: Systems in which CAS# rises before RAS# at the completion of write cycles will not exhibit this erratum. In cases where RAS# transitions high before CAS#, connecting OE# to RAS# will compensate for this erratum.

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, and 03H are affected.

9600007. Operation Delay after Power-Up and Exit from Power-Down or Reset


PROBLEM: With the program/erase voltage (V_{PP}) at 5V, the internal V_{PP} detector may not stabilize for up to 5 μ s (illustrated by t_1 in the figure, *Operation Delay after Power-Up and Exit from Power-Down or Reset*, which follows) after RP# transitions inactive (high). This causes an invalid V_{PP} Level bit indication when reading the Block Status Registers and termination of program, erase or lock block operations due to invalid device V_{PP} error detection. Affected operations include Word Write (40H/10H), Block Erase (20H) and Lock Block (77H).

Note that this erratum only affects systems operating at 5V V_{PP} .

IMPLICATION: 5V V_{PP} power-up/reset time delay to first program or erase operation is impacted.

WORKAROUND: Upon reset, power-up, or wake-up from software sleep or hardware deep power-down, allow 5 μ s (t_1) before initiating a Write/Erase command (as listed earlier) or reading the V_{PP} Level bit of the Block Status Registers (BSR.1). The figure below illustrates this timing requirement (t_1) in more detail.

Operations are initiated by the device on the rising (trailing) edge of the last CAS# pulse in the command sequence. Two-cycle command operations such as Word Write or Erase are initiated on the rising edge of the CAS# pulse corresponding to the Address/Data or Confirm command.



Operation Delay after Power-Up and Exit from Power-Down or Reset

STATUS: Plans to fix this erratum are under evaluation. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H, 03H, and 04H are affected.

9600008. Completion with Command Error Indication

PROBLEM: Systems in which software, after initiating device automation, writes another command(s) to the device before automation completes may initiate unintended device operations.

IMPLICATION: Designs that could encounter this condition include the following:

- Systems that poll for automation completion using the Extended Status Registers (thereby writing the Read Extended Status Register command after initiating automation)
- Systems that write the "Read Compatible Status Register" command after initiating device automation and before reading the Compatible Status Register (This command is actually unnecessary as the device, after receiving commands or command sequences, automatically transitions to a mode where it outputs Compatible Status Register data when read.)
- Systems that use the Erase Suspend command



These unintended operations will produce an invalid command error indication. A command error is indicated by a “1” in the following Status Register bits:

Compatible Status Register

Bit 5: Erase Status

Bit 4: Data-Write Status

Global Status Register

Bit 5: Device Operation Status

Block Status Register (Block 0)


Bit 5: Block Operation Status

This erratum only affects components listed in the Affected Products section.

WORKAROUND: The following options listed below outline possible corrective actions required to avoid this erratum. (Either of the options will eliminate this erratum.)

Option 1: Polling for “Ready” Indication

Systems that poll the RY/BY# pin or WSMS bit (CSR.7) for “Ready” indication before writing another command to the device will not encounter this erratum. This is illustrated in the *Example System Software Flowchart, etc. figure* (which follows), and flowcharts 11-1 and 11-2 (without erase suspend) of the *16-Mbit Flash Memory Product Family User’s Manual*.




Example System Software Flowchart That Will Not Encounter “Completion with Command Error” Condition

Option 2: WE# Pulse Width Restrictions

A WE# pulse width defined by the ranges of parameter t_{WP} in the following table will result in a system that does not exhibit this erratum. (Note: timings are also bounded by specifications in the device datasheet.)

WE# Specifications That Will Not Cause the “Completion with Command Error” Condition

V _{CC} Supply Voltage	t_{WP}
5V	<75 ns
3.3V	<100 ns



Timing Waveform Showing Specification Ranges That Will Not Cause the “Completion with Command Error” Condition

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H and 01H are affected.

9600009. *Non-Serviced Erase Suspend Command*


PROBLEM: If an Erase Suspend command is issued late in the Erase algorithm, it will not be recognized by 28F016XD components listed in the Affected Devices section, and erase will complete. This Erase Suspend command will **not** be discarded.

IMPLICATION: The following conditions are affected by this unserviced Suspend command:


- A. If another Erase command is issued at some time later, the device then assumes that the pending Suspend request is still valid and will automatically Suspend the current Erase.
- B. If any queueable command is in the command queue waiting for execution while another queueable command is in progress, the Write State Machine will suspend its operation after completing the current command. (Refer to *the 16-Mbit Flash Product Family User's Manual*, Section 11-1 for the queueable command list.)

Note that the device will not service the Suspend command if it is powered-down (RP# transitioning low) prior to either condition A or B.

WORKAROUND: A software workaround to this erratum inserts a redundant Resume command (D0H) immediately following any Two-Cycle Command (Word Write, Block Erase, Lock Block, or Upload Status Bits) in the Erase Suspend flowcharts. Modified Erase Suspend to Read Array flowcharts (Figures 11-3 and 11-12 of the *16-Mbit Flash Memory Product Family User's Manual*) detailing this workaround are shown in the *Erase Suspend to Read Array with Compatible Status Register* and *Erase Suspend to Read Array with Extended Status Register* figures, which follow. This erratum results in the *Erase Suspend with Compatible Status Register* flowchart being incompatible with the 28F008SA *Erase Suspend* flowchart.



Erase Suspend to Read Array with Compatible Status Register



Erase Suspend to Read Array with Extended Status Register

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected stepping.

AFFECTED PRODUCTS: All components with Device Version Number 00H are affected.

9600010. *Non-Serviced Block Erase with Stuck Block Status Register*

PROBLEM: If software polls the BS bit of the Block Status Register for block erase completion (BSR.7 = 1) and immediately issues a subsequent block erase command sequence before the WSMS bit of the Compatible Status Register or Global Status Register indicate “Ready” (CSR.7/GSR.7 = 1), the device may not service the subsequent erase operation. This scenario also causes the BS bit of the subsequent block to remain in the “Busy” state (BSR.7 = 0).

IMPLICATION: Block erase operations may be left unserviced.

WORKAROUND: To avoid this erratum, system software should poll CSR.7 (as shown in Figure 11-2 of the *16-Mbit Flash Product Family User's Manual*) or GSR.7, instead of BSR.7, to determine the completion of a block erase operation before issuing subsequent block erase commands.

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, 02H and 03H are affected.

9600011. *WP# Control*

PROBLEM: Block erase can prematurely terminate as the result of hardware RP# activation or V_{CC} transition outside of the normal operating range. In these non-standard scenarios, there exists a small probability that the block's lock-bit will become set, locking the block even though WP# is active (low).

IMPLICATION: Systems may inadvertently lock blocks. The system will not be able to write or erase locked blocks while WP# is held low.

WORKAROUND: System software can detect premature termination of block erase by executing the Upload Status command on device power-up. If both BSR.5 and GSR.5 are set, indicating premature block erase termination, the system should re-attempt erase with WP# inactive (high).

System hardware should be designed to either control WP# (both active and inactive levels must be supported) or should set WP# inactive at all times. Setting WP# always-active (i.e., connecting it to GND) is not recommended as this configuration will not enable recovery from inadvertent lock during premature block erase termination.

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected steppings.

AFFECTED PRODUCTS: All components with Device Version Numbers 00H, 01H, and 02H are affected.

960012. *Components with Fully-Programmed and Locked Blocks*

PROBLEM: Blocks 16–31 are fully-programmed and locked, i.e., when read, the data is 0000H and the BLS bit of the Block Status Register for these blocks is reset (BSR.6 = 0).

IMPLICATION: Blocks 16–31 are fully-programmed and locked.

WORKAROUND: Issuing an Erase Command Sequence (20H followed by D0H) to these blocks with WP# high will reset them to an erased and unlocked state (i.e., when read, the data is FFFFH and the BLS bit of the BSR for these blocks is set (BSR.6 = 1)).

STATUS: This erratum has been fixed. Refer to Summary Table of Contents to determine the affected stepping.

AFFECTED PRODUCTS: All components with Device Revision Number 01H that were tested during Work Week 50 are affected.

SPECIFICATION CHANGES

001. 3.3V and 5V V_{CC} DC Characteristics

PROBLEM: The following tables list DC characteristics that have been improved or that exceed the maximum specifications published in the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet*.

V_{CC} = 3.3V ± 0.3V, T_A = 0°C to +70°C

3/5# Pin Set High for 3.3V Operations

Symbol	Parameter	Max Spec	Max New	Test Conditions
I _{CC3}	V _{CC} RAS#-Only Refresh Current	70 mA	80 mA	V _{CC} = V _{CC} Max CAS# = V _{IH} RAS# = V _{IL} RAS#, Addr. Held Valid and Cycling @ t _{RC(W)} = min Inputs = TTL or CMOS
I _{CC4}	V _{CC} Fast Page Mode Word Read Current	60 mA	70 mA	V _{CC} = V _{CC} Max RAS#, CAS# = V _{IL} CAS#, Addr. Held Valid and Cycling @ t _{PC} = min I _{OUT} = 0 mA Inputs = V _{IL} or V _{IH}
I _{CC5}	V _{CC} Standby Current	130 µA	350 µA ⁽¹⁾ 130 µA ⁽²⁾	V _{CC} = V _{CC} Max, RAS#, CAS#, RP# = V _{CC} ± 0.2V WP#, 3/5# = V _{CC} ± 0.2V or GND ± 0.2V
I _{CC6}	V _{CC} Standby Current	40 mA	15 mA ⁽³⁾	V _{CC} = V _{CC} Max RAS#, CAS# = V _{IL} RAS#, CAS#, Addr. Cycling @ t _{RC} = min Inputs = TTL or CMOS
I _{CC7}	V _{CC} Standby Current (Self-Refresh Mode)	55 mA	10 mA ⁽³⁾	V _{CC} = V _{CC} Max RAS#, CAS# = V _{IL} I _{OUT} = 0 mA Inputs = V _{IL} or V _{IH}
I _{CCD}	V _{CC} Deep Power-Down Current	5 µA	350 µA ⁽¹⁾ 10 µA ⁽²⁾	RP# = GND ± 0.2V

NOTES:

1. These specification values apply to components with a Device Version Number of 00H.
2. These specification values apply to components with Device Version Numbers 01H, 02H, 03H, 04H, and 05H.
3. These specification values apply to components with Device Version Number 06H.

$V_{CC} = 5V \pm 0.5V$, $T_A = 0^\circ\text{C}$ to $+70^\circ\text{C}$
 3/5# Pin Set Low for 5V Operations

Symbol	Parameter	Max Spec	Max New	Test Conditions
I _{CC3}	V _{CC} RAS#-Only Refresh Current	120 mA	145 mA	$V_{CC} = V_{CC}$ Max CAS# = V _{IH} RAS# = V _{IL} RAS#, Addr. Held Valid and Cycling @ $t_{RC(W)} = \text{min}$ Inputs = TTL or CMOS
I _{CC4}	V _{CC} Fast Page Mode Word Read Current	110 mA	130 mA	$V_{CC} = V_{CC}$ Max RAS#, CAS# = V _{IL} CAS#, Addr. Held Valid and Cycling @ $t_{PC} = \text{min}$ I _{OUT} = 0 mA Inputs = V _{IL} or V _{IH}
I _{CC5}	V _{CC} Standby Current	130 μA	350 μA ⁽¹⁾ 130 μA ⁽²⁾	$V_{CC} = V_{CC}$ Max, RAS#, CAS#, RP# = $V_{CC} \pm 0.2V$ WP#, 3/5# = $V_{CC} \pm 0.2V$ or GND $\pm 0.2V$
I _{CC6}	V _{CC} Standby Current	50 μA	15 μA ⁽³⁾	$V_{CC} = V_{CC}$ Max RAS#, CAS# = V _{IL} RAS#, CAS#, Addr. Cycling @ $t_{RC} = \text{min}$ Inputs = TTL or CMOS
I _{CC7}	V _{CC} Standby Current (Self-Refresh Mode)	65 mA	10 mA ⁽³⁾	$V_{CC} = V_{CC}$ Max RAS#, CAS# = V _{IL} I _{OUT} = 0 mA Inputs = V _{IL} or V _{IH}
I _{CCD}	V _{CC} Deep Power-Down Current	5 μA	350 μA ⁽¹⁾ 10 μA ⁽²⁾	RP# = GND $\pm 0.2V$

NOTES:

1. These specification values apply to components with a Device Version Number of 00H.
2. These specification values apply to components with Device Version Numbers 01H, 02H, 03H, 04H, and 05H.
3. These specification values apply to components with a Device Version Number of 06H.

002. 3.3V and 5V V_{PP} DC Characteristics

PROBLEM: The following tables list DC characteristics that exceed the maximum specifications published in the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet*.

V_{CC} = 3.3V ± 0.3V, T_A = 0°C to +70°C

3/5# Pin Set High for 3.3V Operations

Symbol	Parameter	Max Spec	Max New	Test Conditions
I _{PPES}	V _{PP} Erase Suspend Current	50 μA	200 μA	Block Erase Suspend

V_{CC} = 5V ± 0.5V, T_A = 0°C to +70°C

3/5# Pin Set Low for 5V Operations

Symbol	Parameter	Max Spec	Max New	Test Conditions
I _{PPES}	V _{PP} Erase Suspend Current	50 μA	200 μA	Block Erase Suspend

003. AC Read Characteristics

PROBLEM: The AC Read Specifications that deviate from the *28F016XD 16-Mbit (1Mbit x 16) DRAM-Interface Flash Memory Datasheet* are shown below.

V_{CC} = 3.3V ± 0.3V, T_A = 0°C to +70°C

Versions		28F016XD-95			
Symbol	Parameter	Min Spec	Min New	Max Spec	Max New
t _{CAS(R)}	CAS# Pulse Width (Reads)	40 ns	45 ns	∞	∞
t _{RCD(R)}	RAS# to CAS# Delay Time (Reads)	15 ns	15 ns	55 ns	50 ns
t _{CWD}	CAS# to WE# Delay Time	70 ns	75 ns		

SPECIFICATION CLARIFICATIONS

There are no specification clarifications in this Specification Update revision.

DOCUMENTATION CHANGES

There are no documentation changes in this Specification Update revision.