



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-0864-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

April 19, 2007

Intel® Server Board S5000PAL Dual Gigabit Ethernet I/O Expansion Module May Not Initialize After System Restart

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel® Server Board S5000PAL Dual Gigabit Ethernet I/O Expansion Module (product code AXXGBIOMOD)** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

Products Affected

Intel® Server Board S5000PAL Dual Gigabit Ethernet I/O Expansion Module; product code AXXGBIOMOD

Description

Occasionally the NICs on the I/O expansion module may not be available in the BIOS or the operating system.

Note: This issue has only been observed in the Intel® Server System SR1550AL.

Root Cause

The main cause of this issue is incorrect power sequencing on the I/O expansion module. When a DC system reset is performed, the controller on the module may not reset properly which prevents initialization of the external NIC ports. Additionally, based on an update to the design guide for the controller, the external reset circuit was removed from the I/O expansion module. Reset functionality is retained by the reset internal to the controller.

This issue has only been observed in the Intel® Server System SR1550AL due to the unique timings and characteristics of the power supply used.

Corrective Action / Resolution

The design of the I/O expansion module has been changed to correct this issue. This change is outlined in PCN#107383. All modules build per this PCN will not demonstrate this behavior. All affected product has been removed from inventory and replaced with product built per the noted PCN. If you experience this issue on a module built prior to the noted PCN, and would like a replacement, contact Intel using your normal warranty process. Please indicate that you are calling regarding TA #0864 and have the product code (AXXGBIOMOD) and MM# (880518) available.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation