



This Technical Advisory describes an issue which may or may not affect the customer's product

# Intel Technical Advisory

TA-810-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

July 2006

## Baseboard temperature reported by Intel® Server Boards SE7230NH1 using Intel Server Manager 8.40 may exceed upper threshold value

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel® Server Boards SE7230NH1, SE7230NH1LX may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

### Products Affected

Prod Code
SE7230NH1
BNHBB
SE7230NH1LX
BNHBBLX
SR1475NH1
SR1475NH1NA

### Description

Intel® Server Manager 8.40 may report Baseboard temperature sensor events due to an inappropriate threshold value.

### Root Cause

The Intel Server Manager 8.40 installation contains incorrect registry files for the appropriate maximum temperature threshold value for the temperature sensor located between memory slots 1B and 2A. As a result, Intel Server Manager 8.40 may trigger an upper temperature critical event for this temperature sensor shown as one of the two "Baseboard" temperature sensors.

### Corrective Action / Resolution

The registry files for the effected server boards have been updated for Intel Server Manager 8.40. The new registry files are available on support.intel.com. These updated registry files increase the maximum temperature threshold for the temperature sensor from 55 (37H) degrees to 100 (64H) degrees. Note also that these new registry files will incorporate the changes made in TA-801-2 which decreased the CPU core voltage lower threshold. Also, these new registry files rename the temperature sensor (located inside the hardware management module) from "Baseboard" to "Other". The download files can be found at:

<http://support.intel.com/support/motherboards/server/se7230NH1-e/index.htm>

<http://support.intel.com/support/motherboards/server/sr1475nh1-e/index.htm>

To locate the file, (1) click on the "Software & Drivers" link in the left navigation bar, (2) Choose your appropriate Windows\* operating system and click <Go>, and locate the file SE7230NH1\_REG.ZIP

Follow the instructions in the readme.txt file included in the zip package to install and use the registry file.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation