

TA-808-1

5200 NE Elam Young Parkway Hillsboro, OR 97124

April 11, 2006

Intel® Storage System SSR212MA Hard Disk Drive issue.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel® Storage System SSR212MA may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Product	Product Codes
Intel® Storage	SSR212MA
System	SSR212MANA

Description

Intel recently discovered an incompatibility issue with all four Western Digital Hard Disk Drives listed in the 1.4 revision of the SSR212MA Tested Hardware & OS List (THOL) document.

Work Around

- 1) Do not fully populate all twelve drives in the Intel Storage System SSR212MA, with any of the four Western Digital Hard Disk drives, listed in the 1.4 revision of the SSR212MA Tested Hardware & OS List (THOL) document.
- 2) Alternatively, select another drive manufacturer listed in the 1.4 rev of the SSR212MA THOL.

Root Cause

These four Western Digital Hard Disk Drives listed in the 1.4 revision of the SSR212MA Tested Hardware & OS List (THOL) document, do not support Staggered Spin Up (SSU) via pin 11, which is a requirement of the Intel Storage System SSR212MA's RAID Host Bus Adapter. Your SSR212MA may not power up, if all twelve hard disk drives are installed, that do not support pin 11 SSU.

Corrective Action / Resolution

A revised 1.5 THOL is being distributed today with all four Western Digital Hard Disk Drives omitted. Intel is also obtaining new drives from Western Digital that support SSU via pin 11, and will be testing those and adding to a THOL update.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Storage Group Intel Corporation

Copyright © 2006 Intel Corporation.

* Other names and brands may be claimed as the property of others