



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-0861-00

5200 NE Elam Young Parkway
Hillsboro, OR 97124

February 28, 2007

Intel® Server System SR1530CL and Intel® Server System SR1530AH May Have Shipped with Two Identical Rack Handles

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel Server System SR1530CL** and **Intel Server System SR1530AH** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

Products Affected	Affected MM#
SR1530AH	MM# 888104
SR1530AHNA	MM# 888105
SR1530AHLX	MM# 888106
SR1530AHLXNA	MM# 888107
SR1530HAHLX	MM# 887336
SR1530HAHLXNA	MM# 887436
SR1530CL	MM# 888004
SR1530CLNA	MM# 888070
SR1530HCL	MM# 886910
SR1530HCLNA	MM# 887390
SR1530HCLS	MM# 887244
SR1530HCLSNA	MM# 887391

Description

Some shipments of the Intel® Server System SR1530CL and the Intel® Server System SR1530AH contained identical rack handles. Systems may have either two left or two right handles.

Root Cause

The rack handles were in clear bags with no marking to identify if they were right or left rack handles.

Corrective Action / Resolution

To prevent mixing of handles in the future, Intel has added a label to the individual bag that the rack handles are in to identify a right and a left handle.

Recommended Customer Action

If you have received a system with two identical handles, you can contact your Intel representative and request replacement kit part number **TA-0861**. This kit contains one left handle and one right handle.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation