

PARALLEL

Printer	Max. Port Speed	PJL BiDi	Test Page	Comments
Alps DMX800 dot matrix	Low			Will double-space if parallel cable is too long
Alps MD5000	Low			
Apple LaserWriter 16/600 PS	Ultra	No	No	
Apple LaserWriter II	medium	No	No	
Brother HL-1260	Ultra	X	X	
Brother HL-1660e				Customer report of unreliable behavior
Brother HL-660	Ultra	No	Yes	
Brother HL-720	Ultra	No	Yes	
Brother HL-730 DX	Ultra	X	Yes	
Brother MFC-P2000				Print Station customer Report - wont print
Canon BJC-250	medium	n/a	Yes	
Canon BJC-4100	High	Yes	Yes	Does not support BiDi status but prints OK with ECP, PJL, and BiDi all enabled.
Canon BJC-4200				Customer report of compatibility
Canon BJC-4300				Customer report of compatibility
Canon BJC-4550				Print Station Customer Report - wont print
Canon BJC-5000				Print Station Customer Report - wont print
Canon BJC-610				Canon BJC610 operates under Windows printing system which will not operate in the network environment used for this test (Anomaly 1). Requires direct connection to a host computer (Windows printing system needs to be installed on the print server).
Canon BJC-7000	High	No	No	Unable to print in ECP mode
Canon LBP-465				Unfortunately, we have been unable to make the Canon LBP 465 printer work
Canon LBP-660				Unfortunately, we have been unable to make the Canon LBP 660 printer work
Canon LBP-860				Unfortunately, we have been unable to make the Canon LBP 860 printer work
Canon MultiPASS C5500				Print Station Customer Report - wont print
Compaq IJ900				Unfortunately, we have been unable to make the Compaq IJ900 printer work.
DataProducts 1000	Software			
DataProducts B1000/B600	Software			
DataProducts FP2000	Software			
Encad NovaJet 500	High	No		
Encad NovaJet 600/630	High	No		
Encad NovaJet 700	High	No		
Epson Action Laser 1400	Ultra	No	Yes	Does not support BiDi status but prints OK with ECP, PJL, and BiDi all enabled. Driver install loads a status utility that opens with printer and posts error message regarding printer communications. Error message window can be minimized but must End Task to remove (Anomaly 6).
Epson DFX5000	High	No	Yes	
Epson DFX8000	Ultra	No	Yes	
Epson EPL-N1200				Customer report of compatibility
Epson EPL-N2000	Ultra	N	Yes	Unable to print in ECP mode
Epson FX-2170				Customer report of compatibility
Epson FX-870				Customer report of compatibility
Epson LQ 570+	Low	No	Yes	
Epson Stylus color 1520				Customer report of compatibility
Epson Stylus color 200	High	No		Does not support BiDi status but prints OK with ECP, PJL, and BiDi all enabled. Printer driver installs with its own spooler software. To work with NetPort Express a local Printer Port needs to be captured and the Windows Print Manager needs to be enabled in the Epson Spooler Queue Setup (Anomaly 7).
Epson Stylus color 600	Low	No	No	
Epson Stylus color 740	medium	No	No	Older drivers may work however, new drivers do not work.

PARALLEL

Printer	Max. Port Speed	PJL BiDi	Test Page	Comments
Alps DMX800 dot matrix	Low			Will double-space if parallel cable is too long
Alps MD5000	Low			
Apple LaserWriter 16/600 PS	Ultra	No	No	
Epson Stylus color 800	High	No	No	Open Epson Spool Manger 4 and go to Q/Setup. Check the box which says "use print manger to print" For Win98 machines it may be necessary for the user to manually add the .icm files in order to populate the Color Management profiles.
Epson Stylus color 900	High	No	No	Install driver only not the port monitor. Install printer to LPT1 the redirect to UNC of Netport.
Epson Stylus color ESC/P2	High	No	No	
Epson Stylus Photo 750	medium	No	No	
Genicom 4410XT	Software Controlled			
Genicom 4490XT	Software Controlled			Customer report: Strobe pulse is incorrect, Genicom has fix
HP 2000 C	medium	No	Yes	
HP 2500	Medium	No	Yes	Customer report: conflict with HP monitor
HP 3100				not supported see solution ID 1.0.32875484.1988473
HP 4000	Ultra	No	Yes	
HP 4000TN	Ultra	No	Yes	
HP 5000	Ultra	No	Yes	Results are the same for both PCL-XL and PS drivers. Could print but not achieve Bi-di communications through AppleTalk
HP 5000N	Ultra	No	Yes	
HP Design Jet 700 plotter	Medium	No	No	
HP Design Jet 750c/755CM	Medium	No	No	
HP DeskJet 1000C/1100C	medium	No	No	Must click capture port in printer properties to get this printer to print.
HP DeskJet 1120C	medium	No	No	Must click capture port in printer properties to get this printer to print.
HP DeskJet 1600 CM				Customer report of compatibility
HP DeskJet 400	High	No	No	Fails to print with ECP on (regardless of other settings). Test page will not print lpt1 or lpt2 - error light blinks - power cycle printer to clear.
HP DeskJet 400 Euro PS				Unable to print
HP DeskJet 540	High	No	Yes	
HP DeskJet 660C	High	No	Yes	
HP DeskJet 690C	Ultra	No	Yes	
HP DeskJet 692C	High	No	Yes	
HP DeskJet 694C	High	No	Yes	
HP DeskJet 697C	medium	No	Yes	Run setup program, install printer to LPT1. Change printer properties to Intel Network port..\\printserver\share
HP DeskJet 720C/722C	High	No	No	
HP DeskJet 810C	medium	No	Yes	Run setup program, install printer to LPT1. Change printer properties to Intel Network port..\\printserver\share
HP DeskJet 812C	medium	No	Yes	Run setup program, install printer to LPT1. Change printer properties to Intel Network port..\\printserver\share
HP DeskJet 820 cse	medium	No	Yes	
HP DeskJet 830C	medium	No	Yes	Run setup program, install printer to LPT1. Change printer properties to Intel Network port..\\printserver\share
HP DeskJet 855C	medium	No	Yes	
HP DeskJet 870 Cxi	medium	No	Yes	
HP DeskJet 870Cse	High	No	Yes	Prints with PJL BiDi enabled but BiDi status not supported. Received Spool32 error once during testing. Must be configured to LPT1 then change port properties to UNC of Netport
HP DeskJet 880C	medium	No	Yes	Do not use setup program. Use *.inf appropriate for OS. Install to LPT1 and run Intel APW.

PARALLEL

Printer	Max. Port Speed	PJL BiDi	Test Page	Comments
Alps DMX800 dot matrix	Low			Will double-space if parallel cable is too long
Alps MD5000	Low			
Apple LaserWriter 16/600 PS	Ultra	No	No	
HP DeskJet 890C	Medium	No	Yes	
HP DeskJet 895C se	medium	No	Yes	
HP DeskJet 930C	medium	No	No	Some customer reports of incompatibility
HP DeskJet 970Cxi	High	No	Yes	Tested with network driver (Corporate Driver) provided on CD. Do not use home user driver. Printer status is unreliable.
HP LaserJet 1100xi	medium	No		
HP LaserJet 3100se				Could not configure to communicate with NetPort Express . Though not specifically identified as a Windows printing system, port communications apparently require hard parallel port communications.
HP LaserJet 4/4M/4Plus	Ultra	No	Yes	
HP LaserJet 4000	Ultra	No	Yes	
HP LaserJet 4L	Ultra	No	Yes	
HP LaserJet 4V/MV	Ultra	No	Yes	
HP LaserJet 5	High	No	Yes	
HP LaserJet 5/5M Color				Unable to print
HP LaserJet 5L	High	No	Yes	
HP LaserJet 5P	Ultra	No	Yes	
HP LaserJet 5Si/5Si-Mx	High	No	Yes	ECP/BI-DI cannot be used together
HP LaserJet 6L/6Lse/6Lxi	Ultra	No	Yes	
HP LaserJet 6p/6mp/6Pse/6F				*Print Station customer report, unable to print
HP LaserJet 8000				*Customer report of compatibility
HP LaserJet II, all models	Low			May work unreliably at medium speed.
HP LaserJet III, all models	Low			May work unreliably at medium speed.
HP Office Jet 350	none			Could not configure to communicate with NetPortExpress. Though not specifically identified as a Windows printing system, port communications require hard parallel port communications. Setup warns user that direct LPT connections is required for communication with device. Does print a test page when NetPortExpress test page button is pressed.
HP Office Jet 570	Ultra	No	Yes	
HP Office Jet C-5300A	medium	No	Yes	
HP Office Jet Pro 1150C	High	No	No	
HP PhotoSmart	Low	No	No	Must be configured to LPT1 then change port properties to UNC of Netport
IBM Laser Printer 10L 4029	High	No	Yes	
IBM Laser Printer 4019	Ultra	No	Yes	
IBM Network Printer 12	Ultra	No	No	
Lexmark 4079 Plus	Medium	No	No	
Lexmark InkJet				
Lexmark Optra E	Low	Yes	Yes	
Lexmark Optra L	Ultra	Yes	Yes	
Lexmark Optra R+	Ultra	Yes	Yes	
Lexmark Optra Rx	Ultra	Yes	Yes	
Lexmark Optra S 1650	Ultra	Yes	Yes	ECP/BI-DI cannot be used together
Lexmark Optra S 1850	Ultra	Yes	Yes	
Lexmark Optra S 1855	Ultra	Yes	Yes	
Lexmark Optra S 2450	Ultra	Yes	Yes	ECP/BI-DI cannot be used together
Lexmark Optra S 3450	Ultra	Yes	Yes	
Lexmark Optra SC 1275	Ultra	Yes	Yes	

PARALLEL

Printer	Max. Port Speed	PJL BiDi	Test Page	Comments
Alps DMX800 dot matrix	Low			Will double-space if parallel cable is too long
Alps MD5000	Low			
Apple LaserWriter 16/600 PS	Ultra	No	No	
MicroLaser Pro/18	medium	No	Yes	
NEC Silent Writer 1760	medium	No	Yes	
NEC Super Script 1260c	Medium	No	Yes	
NEC Super Script 860	Medium	No	Yes	
Okidata Microline 380	Ultra	No	Yes	
Okidata Microline 395	Ultra	No	Yes	
Okidata Microline 520	Ultra	No	Yes	
Okidata OL 1200, 1200 PS	High	No	Yes	
Okidata OL 400e	High	No	Yes	Systems hangs on Ultra setting forcing a power off situation which results in Scandisk finding file errors upon reboot.
Okidata OL 810e	Ultra	No	Yes	
OkidataOkipage 4W	medium	No	Yes	*Not supported by NT
Panasonic KX-P6500	Ultra	No	Yes	
QMS Kiss	Ultra	No	Yes	
QMS MagicColor Laser 2	Software	No	No	Do not use QMS port monitor software
Tektronics Phaser 350	Ultra	No	No	
TI MicroLaser 600	Ultra	No	No	
TI MicroLaser Power Pro-8	High	No	Yes	
TI MicroLaser Pro 600	Ultra	No	No	
TI MicroLaser Win4				TI MicroLaser Win/4 operates under Windows printing system which will not operate in the network environment. Requires direct connection to a host computer.
Xerox 4505ps	Ultra	No	Yes	
Xerox DocuPrint 4508				Customer report of compatibility
Xerox DocuPrint 4510	Ultra	No	No	
Xerox DocuPrint N32	High	No	No	Could print but not achieve Bi-di communications through AppleTalk (for both Laserwriter and Xerox icon in Chooser).
Xerox DocuPrint P12	Ultra	No	Yes	
Xerox WorkCentre XD105f				Unfortunately, we have been unable to make the Xerox WorkCentre printer work.
Xerox WorkCentre XE80				Unfortunately, we have been unable to make the Xerox WorkCentre printer work.

Note: Unless indicated, the driver used was included with the printer or in the OS printer wizard at the time of this testing.

Max Port Speed = Maximum recommend port speed. Other speeds may work but produce inconsistant results.
 Bi-di/PJL= The printer was returns front panel messages within Netport(R) Manager when these options are selected.
 Test Page = Using the Test page/Diag page button on the print server produces a test page