

Motherboard Logo Program (MLP)

# Intel® Desktop Board

## DH61H0

---

# MLP Report

09/20/2012

**Purpose:**

This report describes the DH61H0 Desktop /Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others

Copyright © 2009, Intel Corporation. All rights reserved.

# Contents

---

<b>Introduction .....</b>	<b>4</b>
Terms and Definitions.....	4
<b>Desktop Board Configuration .....</b>	<b>5</b>
Desktop Board DH61KV Final Configuration Report: Completion of MLP .....	5
Board Information.....	5
Product Code.....	5
Processor .....	5
Motherboard .....	5
System Memory.....	5
Power Management.....	5
Operating System Tested.....	5
Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit.....	<b>Error! Bookmark not defined.</b>
Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit.....	6
Windows Logo Kits Used (WLK) .....	6
Errata and Contingencies .....	6
Test Notes .....	6

# Introduction

---

## Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WHCK	Windows Hardware Certification Kit
MLP	Motherboard Logo Program. For further information see: <a href="http://msdn.microsoft.com/zh-Tw/library/windows/hardware/gg463010">http://msdn.microsoft.com/zh-Tw/library/windows/hardware/gg463010</a>
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s</a>

# Desktop Board Configuration

---

## Desktop Board DH61H0 Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

### Board Information

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)
DH61H0	H0H6110H.86A.0804.2012.0827.1504	N/A - all technologies logo'd
<b>Processor</b>		
Speed	2.80GHz	
Family	Intel Core I5	
Bus Speed	100 MHz	
<b>Motherboard</b>		
Board AA #	G62445-100	
Board FAB #	A	
<a href="#">* This report applies to the production FAB revision; Please consult your Intel Corporation representative to clarify the motherboard revision you intend to perform logo testing if not the same.</a>		
<b>System Memory</b>		
Speed	Dual Channel, DDR3, 1333MHz	
Memory Type	DIMM elixir DDR3 1333/2GB	
Connector Type	DDR3, 240 Pin	
<b>Power Management</b>		
BIOS Default	S3	
<b>Operating System Tested</b>		
	<b>Check Tested</b>	<b>Comments</b>
Windows 8 and 64-bit	<input checked="" type="checkbox"/>	Windows 8 Ultimate 9200

---

<sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

## Onboard Integrated Devices and Driver for Windows 8 64-bit

Technology	OS	Version	Package version
Chipset Update Utility Intel® Chipset Software Utility	Windows 8 64-bit	V9.3.0.1021	V9.3.0.1021
Graphics Intel® HD Graphics	Windows 8 64-bit	V8.15.10.2792	V8.15.10.2792
Audio Realtek	Windows 8 64-bit	V6.0.1.6680	V6.0.1.6680
LAN Realtek	Windows 8 64-bit	V8.2.612.2012	V8.2.612.2012
MEI Intel® Management Engine Interface	Windows 8 64-bit	V8.1.0.1263	V8.1.0.1263

## Windows Hardware Certification Kit Used (WHCK)

Microsoft website: <http://msdn.microsoft.com/library/windows/hardware/hh833788>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 8 64-bit	WHCK 9200 QFE 004	WHCK 9200 QFE 004

## Errata and Contingencies

Operating System	Falling Test	Expiry Date	ID Number	Type	Error Description
Windows 8 64-bit	None				

## Test Notes

Operating System	Test	Description
Windows 8	BIOS download	Internal: <a href="http://bios.intel.com/downloads/">http://bios.intel.com/downloads/</a> External: <a href="http://www.intel.com/">http://www.intel.com/</a> click on Support and Download
Windows 8	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings.

		System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component (Except CIR) Drive Configuration: Set to AHCI Chipset Configuration: Enable HPET ACPI Suspend State: Set to <S3 State> Boot Device Priority: set <Hard Disk Driver> to first
<b>Windows 8</b>	WHCK WHQL test	<a href="http://msdn.microsoft.com/zh-TW/library/windows/hardware/hh852367">http://msdn.microsoft.com/zh-TW/library/windows/hardware/hh852367</a>
<b>Special H/W that use to PASS the test</b>	None	None