


Intel Corporation  
5200 N.E. Elam Young Parkway  
Hillsboro, OR 97124



July 12, 2007

Dear Intel EPSD server product customer:

In order to support the new Intel® Xeon® processors based on 45nm technology, EPSD will be updating its current lineup of Intel® Server Boards and Intel® Server Systems based on the Intel® 5000 Chipset.

With this update EPSD will be changing the product codes of the affected Intel® Server Boards and Systems to allow customers to easily identify which products support both the new 45nm-based products as well as the existing Intel® Xeon® 5000, 5100, and 5300 series processors.

While changing a product code may lead customers to assume that this is a major change to the affected products, Intel views this update as a minor modification which should be considered low risk. Intel expects that the updated products will be fully backward compatible with the previous versions, and should not require extra validation.

Shortly after the updated products are released, Intel will cease to produce the older versions of the Intel® Server Boards and Intel® Server Systems listed below. Final purchases orders for the older products will need to be received by September 7, 2007 with confirmed delivery by November 9, 2007.

This notification affects the following Intel® Server Board and Intel® Server System product codes:

**Intel® Server Boards (Single Pack)**

<b>Current Product Code</b>	<b>Current MM#</b>
S5000PSLROMB	886037
S5000PSLSAS	886036
S5000PSLSATA	886032
S5000XVNSAS	886042
S5000XVNSATA	886040
S5000VSA4DIMM	885886
S5000VSASAS	886310
S5000VSASATA	885885
S5000VSASCSI	885888
S5000PAL	885478

**Intel® Server Boards (OEM Bulk Pack)**

<b>Current Product Code</b>	<b>Current MM#</b>
BB5000PSLROMB	890274
BB5000PSLSAS	890273
BB5000PSLSATA	890275
BB5000XSLSATA	890279
BB5000XVNSAS	890278
BB5000XVNSATA	890276
BSA2BB	891196
BSA2SASBB	891199
BSA2VBB	891198
BB5000PAL	890143
BB5000XAL	890144
S5000VCLSASBB	890507



**Intel® Server Systems**

<b>Current Product Code</b>	<b>Current MM#</b>
SR1500AL	885480
SR1500ALNA	885482
SR1500ALSAS	885481
SR1500ALSASNA	885483
SR1550AL	885484
SR1550ALNA	885486
SR1550ALSAS	885487
SR1550ALSASNA	885486
SR2500ALBRP	885488
SR2500ALBRPNA	885498
SR2500ALLX	885489
SR2500ALLXNA	885499
SR2500ALOEM	885496
SR2500ALOEMNA	885500
SR1530CL	888004
SR1530CLNA	888070
SR1530HCL	886910
SR1530HCLNA	887390
SR1530HCLS	887244
SR1530HCLSNA	887391
SR2520SAF	886904
SR2520SAFNA	887435
SR2520SAX	886991
SR2520SAXNA	887434
SR2520SAXS	886905
SR2520SAXSNA	887432

**Replacement products:**

All of the products listed above will be available in an updated version, and can be ordered using the product codes below. As mentioned above it is Intel's expectation that the products listed below will be fully backward compatible with the earlier versions.

**Intel® Server Boards (Single Pack)**

<b>Current Product Code</b>	<b>Current MM#</b>	<b>New Product Code</b>	<b>New MM#</b>
S5000PSLROMB	886037	S5000PSLROMBR	891983
S5000PSLSAS	886036	S5000PSLSASR	892051
S5000PSLSATA	886032	S5000PSLSATAR	891984
S5000XVNSAS	886042	S5000XVNSASR	891986
S5000XVNSATA	886040	S5000XVNSATAR	891999
S5000VSA4DIMM	885886	S5000VSA4DIMMR	892063
S5000VSASAS	886310	S5000VSASASR	892065
S5000VSASATA	885885	S5000VSASATAR	892061
S5000VSASCSI	885888	S5000VSASCSIR	892064
S5000PAL	885478	S5000PALR	891957



**Intel® Server Boards (OEM Bulk Pack)**

<b>Current Product Code</b>	<b>Current MM#</b>	<b>New Product Code</b>	<b>New MM#</b>
BB5000PSLROMB	890274	BB5000PSLROMBR	892008
BB5000PSLSAS	890273	BB5000PSLSASR	892012
BB5000PSLSATA	890275	BB5000PSLSATAR	892013
BB5000XLSATA	890279	BB5000XLSATAR	892015
BB5000XVNSAS	890278	BB5000XVNSASR	892016
BB5000XVNSATA	890276	BB5000XVNSATAR	892017
BSA2BB	891196	BSA2BBR	892073
BSA2SASBB	891199	BSA2SASBBR	892075
BSA2VBB	891198	BSA2VBBR	892074
BB5000PAL	890143	BB5000PALR	891958
BB5000XAL	890144	BB5000XALR	891956
S5000VCLSASBB	890507	BBS5000VCLSASR	892083

**Intel® Server Systems**

<b>Current Product Code</b>	<b>Current MM#</b>	<b>New Product Code</b>	<b>New MM#</b>
SR1500AL	885480	SR1500ALR	891962
SR1500ALNA	885482	SR1500ALRNA	892025
SR1500ALSAS	885481	SR1500ALSASR	891963
SR1500ALSASNA	885483	SR1500ALSASRNA	892029
SR1550AL	885484	SR1550ALR	891970
SR1550ALNA	885486	SR1550ALRNA	892034
SR1550ALSAS	885485	SR1550ALSASR	891967
SR1550ALSASNA	885487	SR1550ALSASRNA	892046
SR2500ALBRP	885488	SR2500ALBRPR	891964
SR2500ALBRPNA	885498	SR2500ALBRPRNA	892030
SR2500ALLX	885489	SR2500ALLXR	891965
SR2500ALLXNA	885499	SR2500ALLXRNA	892032
SR2500ALOEM	885496	SR2500ALOEMR	891966
SR2500ALOEMNA	885500	SR2500ALOEMRNA	892033
SR1530CL	888004	SR1530CLR	892052
SR1530CLNA	888070	SR1530CLRNA	892053
SR1530HCL	886910	SR1530HCLR	892054
SR1530HCLNA	887390	SR1530HCLRNA	892057
SR1530HCLS	887244	SR1530HCLSR	892060
SR1530HCLSNA	887391	SR1530HCLSRNA	892047
SR2520SAF	886904	SR2520SAFR	892236
SR2520SAFNA	887435	SR2520SAFRNA	892292
SR2520SAX	886991	SR2520SAXR	892249
SR2520SAXNA	887434	SR2520SAXRNA	892290
SR2520SAXS	886905	SR2520SAXSR	892251
SR2520SAXSNA	887432	SR2520SAXSRNA	892291

Intel Corporation  
5200 N.E. Elam Young Parkway  
Hillsboro, OR 97124



Summary:

1. This product discontinuance notification is effective July 13th, 2007.
2. Final purchase orders for the affected products must be placed by Sept 7, 2007.
3. The final quantity to be shipped must specify a customer request date (CRD) no later than November 9, 2007.

Final purchase orders are non-cancelable and non-returnable, notwithstanding any conflicting terms in our quotes, purchase order acknowledgment or Distributor agreements.

Contact your local Intel Sales Office or Distributor if you require more information or need assistance in selecting a replacement product.

Sincerely,

EPSD Marketing